

COPY

# LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780

RE-CONSTITUTED 1834

## Certificate of Class

**Twin Screw Motorship "KURWINA"**

Official Number 196148 Port of Registry Port Moresby

Owners Burns, Philp (New Guinea) Ltd.,

Builders, and where and when built Taikoo Dockyard & Engineering Co. Ltd., of Hong Kong Ltd.,  
Hong Kong, May, 1961

REGISTERED TONNAGES

Gross 227.02

Net 99.75

MOULDED DIMENSIONS

Length 92' 0"

Breadth 22' 0"

Depth 10' 0"

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 26th May, 1961 at Hong Kong and on the 21st July, 1961 at Port Moresby, N.G. in a fit and efficient condition and in accordance with the Rules; also that she has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character

**100A1**  
 New Guinea Coasting Service  
 Deep tanks forward - Oil FP above  
 150°F

subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical.....	3	feet.....	4½	inches (T).	Winter	}	-	feet.....	-	inches (WNA).
Summer.....	3	feet.....	6¼	inches (S).	North Atlantic		}	-	feet.....	-
Winter.....	-	feet.....	-	inches (W).	Allowance for fresh water for all freeboards	}		1¼	inches	

Witness my hand,

W.J.F.  
 Secretary,

*R. M. T.*  
 Deputy Chairman.


71, Fenchurch Street, London, E.C.3. 1st September, 1961.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

H. 2



Lloyd's Register  
 Foundation

010846-010857-0198