

HONG KONG 28246

CABLE ADDRESS: MARINE

Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER

236, ALEXANDRA HOUSE
P. O. BOX 463
HONG KONG

20th July, 1961.

The Secretary,
Lloyd's Register of Shipping,
LONDON.

Dear Sir,

HKG 13 117

RECEIVED

24 JUL 1961


Motor vessels "Kalili" & "Kurwina"
Taikoo Dockyard - Yard Nos. 485 & 486
Hong Kong Rpt. 13 Nos. 16252/3 Ans'd.

see FE of Kalili

We forward for your attention copies of the manufacturers' Works Test Certificates related to the four electric generators installed in the above vessels. These certificates have been produced after considerable delay on the part of the makers, The Lancashire Dynamo & Crypto, Ltd., and in spite of assurances to the Dockyard installing these machines that they would be in compliance with the Rules, it is now apparent that they do not meet with the requirement that under full load conditions the voltage across the fields must not exceed 86% of the generated voltage. The manufacturers state that in this respect they have been supplied to normal commercial requirements, and the voltage across the fields is in the order of 98% for generators Nos. 33N026/7 and 94½% for generators Nos. 33N028/9.

These two vessels are now in service in New Guinea, and we would be glad to have your advice regarding procedure to be adopted in these circumstances.

Yours faithfully,


J.L.V. Whittle
For the Surveyors.

Enclosed 2 Test Certificates.

JLVW:syp



© 2021

Lloyd's Register
Foundation

010846-010857-0204

ACCEPT IN
THIS INSTANCE
- SEE ORIGINAL OF
LETTER ON FE "KALILI"
& REPLY of 28/7/61



© 2021

Lloyd's Register
Foundation