

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME

GB

"KURWINA"

REPORT

L.A.

No. 4574

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

This ship was built in Hong Kong for New Guinea Coasting Service and the class *100A1 "New Guinea Coasting Service" "DTf - Oil FP above 150° F" with record of 'DS 5,61' recommended WHEN a report has been received of its satisfactory condition on arrival within the service limits.

For further particulars see Endorsement dated 13.7.61.

The Lloyd's Agents (Port Moresby) Surveyors report (7,61), ship generally examined afloat and found in satisfactory condition.

IT IS THEREFORE SUBMITTED the ship is now eligible to be classed *100A1 "New Guinea Coasting Service" "DTf - Oil FP above 150° F" with record of 'DS 5,61' assigned.

*100A1 "New Guinea Coasting Service"
"DTf - Oil FP above 150° F"
DS 5,61

PARTICULARS FOR R.B.
As per Endorsement
dated 13.7.61.

REPT
8

DA.

25.8.61.



© 2021

Lloyd's Register
Foundation

010846-010857-0207