

17th September, 1954.

HULL

60513,27,31,37,41. As recommended.

60492 "HANDYMAN" As recommended, the contents of your letter of the 4th instant having been noted.

60512 "BIDDY" As recommended, except that as it is concluded the upper end of the rudder stock remains slightly twisted, this item has been made an Endorsement, Category (B). I shall, however, be glad to receive your confirmation on the above point.



© 2021

Lloyd's Register
Foundation

010858-010865-0014