

2 E

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"BIDDY"

REPORT

Hull

No. 60512

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Object of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS~~

This Survey, due 7,54 ~~partly~~ ^{now} held, and vessel examined in ~~drydock~~ ^{drydock}

~~completed, and the following repairs carried out (due to~~):-

It is submitted the vessel is eligible to remain as classed, with

notation of BS 8,54

as recommended.



© 2021

Lloyd's Register Foundation

14.9.54.

010858-010865-0017

all found or placed in good condition. Safety valves adjusted up to above stated pressure.