

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name LEEWANA Official No. _____Port of Registry PANAMAThis ship has been under survey at Sydney NSWon 25 June 1957 and the following alterations to the conditions ofassignment of loadlines have now been effected/~~found~~:— in accordance withThe Secretary's instructions to the Sydney Surveyors for new service
without geographical restrictions:Nº 1 HATCH : Beams reinforced with $4 \times \frac{1}{2}$ " flat bar on
lower side.

Locking bars supplied & fitted.

(per Sydney Surveyors C11 (b) 25.6.57).

A copy of this Report has been placed on board.

