

LLOYD'S REGISTER OF SHIPPING

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "LEEWANA"

Official No. 3170-HK

Port of Registry Panama.

This ship has been under survey at Hong Kong,

on 5th February to 7th August, 1958, and the following alterations to the conditions of assignment of loadlines have now been effected/found:—

Alterations now effected on Conversion to Oil Fuel:—


Former coal bunker hatchway on bridge deck plated over.

Air pipes - Two (1 p. & 1s.) at 5" dia. from P. & S. bunkers - 6'-6" above upper deck, strongly secured.

Two (1 p. & 1s.) at 3" dia. from P. & S. settling tanks, 36" above bridge deck.

All air pipes fitted with wire-gauzes and canvas covers.

Engine-room skylight covers replaced with strongly constructed steel covers.



J.L.V. Whittle
Surveyor to Lloyd's Register
HONG KONG.

7th August, 1958.

Noted
ARL
10.10.58

A copy of this Report has been placed on board.

5m. 0.56. T.



© 2021

Lloyd's Register
Foundation

010866-010873-0006