

LLOYD'S REGISTER OF SHIPPING

Enclosure.

Bellmansgatan 15

RECEIVED

Stockholm SÖ 18th November, 1960.

21 NOV 1960

. (S)

The Secretary,
LONDON.

Dear Sir,

"LUTZKENDORF".

In reply to your classing letter of 18th October, 1960, we have to report that, as the Owners were unable to produce recent interim certificates showing a condition of class against the lower cylinder covers of Nos. 1 and 7 units, and as our copy of the "Special Reasons List", No. 173, omitted to mention these items, they were not examined at this time. In accordance with your instructions we have issued an amended Interim Certificate, a copy of which is enclosed.

We have to explain that the delay in reporting the surveys was due to extreme pressure of work at that time, also absences on account of holidays and illness.

Yours faithfully,
THE SURVEYORS, Stockholm.

© 2021

Lloyd's Register
Foundation

ER.

CLASSIFICATION

H

M

Owners should be advised that the metallock repairs to nos 1 and 7 bottom cylinder covers should be worn as early as possible also that the belt from the C/E regarding setting of ex. gas SVs is awaited

@ 23/11/60



© 2021

Lloyd's Register
Foundation

LOCKH
820,
LTYZK
tter
TNER
rtt1f