

JUL 1963

Ship's name "MOBIL RADIANT"

Port

DRB

No. 10346

Last survey date 24.6.63


Class is subject to

NIL

Damage stated to have been sustained by the outboard turbo generator set due to overspeeding.

Some rotor blading found defective and cut out. Rotor tested in lathe for truth and found in order, *balanced* and replaced. Governor gear overhauled and placed in good order. On completion this set tried under full load conditions and all found in order. Recommended the outboard turbo generator turbine be specially examined at next dry docking and by 6.64.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as recommended.



Sub © 2021

9.7.63

Lloyd's Register
Foundation