

20783

MELBOURNE

8th August, 1963

"MOBIL RADIANT"

17598

of Panama

repairs to damage to the stbd boiler stated to have occurred on the 19th July, 1963.

=====

===== subject to the rear wall tubes in the
stbd boiler being specially examined at the next boiler survey.

W.R. Rightfield
W.R. RIGHTFIELD.



© 2021

Lloyd's Register
Foundation

010874-010881-0087

63.

ae
s
S.W.,
on
sulation

bowed
amined
ined

rostati

st be given.
ding items
ords Dept.,
terations in