

Surveyors.....

Received from Chief Surveyors.....

"POZA RICA

REPORT L.Au.

No. 5497.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

Reports which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been carried out and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from sub-Committee's Report, 24/5/92.).

by Diego & Dan Rhrs.

When due

L.Au.

The Secretary, N.Y.R. should be requested to obtain
 furnish the L.Au. Surveyors comments as to why the
 sounding device in the aft pump room is unsafe, it being
 noted that the device is not in accordance with the Socy's.
 local reqs. for Tankers. If such is the case then the enditic
 ss should have appeared in the Rpt 9. The surveyor should also
 be asked to state whether the shell plating has been pierced to
 make this
 note.

ENGINEER SURVEYORS TO NOTE

Surveyors should be referred to Que 1808
 + comments requested for

See letter
7.12.56.© 2021
Royal Register
Foundation

22/10/56.