

Report to Chief Surveyors \_\_\_\_\_ Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl T.S. M/V "MARTHA E. ALLEN" Report Cl No. 43

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey 1<sup>st</sup> Entry When due Revised Rules Rules

✱ 100A.1. (Steel) "for Service on the Great Lakes" Carrying Petroleum in Bulk  
1D<sup>1</sup> (Ste). Longitudinal framing at bottom and at deck.  
Cell D.B v E 60' 40t F.P.T. 64t, A.P.T. 68t.

F.K. 11 B.H. Plyds A CP  
P. 85' TRUNK 197'. F 52'. Machinery aft.



010933-010942-0160

Floorsevery	breadth and thickness of Middle line Streak	96" x 50"
	Thickness of material in Middle	