

there a drain arrangement fitted at the lowest part of each receiver

motor Eng. No. 4475  
No.

Made by

Kronpunkt Motor Fabrik, Aus.

American S.D. 60, Cleveland, Ind. No. 803.

Aus. Report No. 10975

It is submitted that this Report be ~~returned~~ <sup>forwarded</sup> to  
the Cleveland Surveyors for their guidance and  
for completion.



Date

© 2021

Lloyd's Register  
Foundation

010933-010942-0179

and brass and bolts, 1 set of main bearing.

Copy sent  
Cleveland  
11.5.28