



LLOYD'S REGISTER OF SHIPPING

RECEIVED

- 2 JUN 1958

Ans'd

20, Sathorn Road, Bangkok

26th May, 1958.

C. KNOTT, B.Sc.
SURVEYOR

Reference

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
London, E.C. 3.

Dear Sir,

Lighters M.L. 1 & M.L. 3.


These lighters are again in the process of sale, and the new buyers would like them to be reclassified. These vessels were classed before the war, and went through a very big repair 18 months ago, and have not been used since. I would be much obliged if you would let me know if they can be reclassified and what extent will be required to put them into class.

When the sale is completed the Changnam will be docked for tailsaft and boiler survey.

Yours faithfully,

D.C. Knott.

010982-010991-0184



© 2021

Lloyd's Register
Foundation

SR

H

CLASSIFICATION

See D.C. 11000.

Memo. R. 1. 8

These registers are again in the process of sale, and like them to be recast. These registers are again in the process of sale, and like them to be recast. These registers are again in the process of sale, and like them to be recast.

Registers No. 1 & No. 3.

DEPT. 217

LONDON, E.C. 3.
The Secretary of Shipping,
Lloyd's Register Street,
London, E.C. 3.

Set up, 1888.

30, South Quay, Bangkok

RECEIVED
LLOYD'S REGISTER OF SHIPPING

© 2021

Lloyd's Register
Foundation

Gener
this s
surve

Have the T
Have the T
Inner Bott
Stringers
Keelsons
Floors
Transverse
Longitudin
Reverse
Frames

Outside P
Beams & L
Joistings
Faulking c
Decks
ASSENT
Faint
sem
Bene