

afloat,

5c.9.30.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Barge "SERVICE SHELL VI"* Rpt. *Rou* No. *1033*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st Long

Transverse No. *1484*

Depth "d" *✓*

Framing: Table No.

Description *Bulb angle frames as approved*

2nd Longitudinal No. *4773*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *11.22*

Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100A.1 (Steel) "Barge"
1 D^o (Stl)
F.K., 7 B.H., Lloyds A R.P.


"Carrying oil fuel in Bulk, F.P. above 150° F"
"Carrying Petroleum in Bulk"
for River and Estuary Services

See Endorsement
Date 2.2.31

L. Rou
1/1/31

31.12.30
6.2.31

It is concluded the tests for the ~~obtain~~ cable are as requested by the Rules but the surveyor should be requested to state if this is so.



© 2021

Lloyd's Register Foundation

010992-011000-0205