

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 28 MAR 1954... Port of LIVERPOOL
 No. in Reg. Book. 07649 Survey held at FLEETWOOD Date, First Survey 8 Last Survey 19TH MARCH, 1954
 on the Wood Iron or Steel S.T.A. "DINAS" (No. of Visits...)

TONNAGE :- Built at S. Shields By whom C. Rennoldson & Co. When 1919 8 MONTHS
 GROSS 275 Owners Dinas Steam Trawling Co. Ltd. Owners' Address _____
 UNDER DK. 246 Managers _____ Port belonging to Fleetwood
 NET 120

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Wyre Dock Destined Voyage _____
 Cell/Dor/DBa _____ feet; uE & B _____ feet; f _____ feet
 total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ feet _____ tons.

N.B. - All alterations in the existing records should be underlined.

Last Report, No. 137635 Port Liv.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
<u>*100A1 Stm.</u>	<u>LMC 9,49</u>
<u>Trawler 7,53</u>	<u>BS 3,53</u>
<u>ssMil. 2nd No. 3-</u>	<u>TS CL 3,53</u>
<u>3,45</u>	
<u>ssFlt. -9,49</u>	

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined None reported Society's Freeboard (if assigned) as painted on Ship and now verified } _____ ft. _____ ins.
 Was a damage report made by anyone else? if so, by whom? _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR Commencement of Special Survey.

Now done: Vessel examined afloat. Spaces below boilers examined, & all found in good condition.

To complete the Special Survey all Rule requirements remain to be dealt with, except the item above. The owner's superintendent states the survey will be completed in June or July 1954.

SUMMARY OF DAMAGE REPAIRS :-

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month _____ Year _____
Coamings	Cement or Asphalt	Oil Bunkers	
Beams & Fastenings	Rudder <u>bonified</u>	Scupper <u>to</u> <u>Itan</u>	Boats <u>Above.</u>
Outside Plating	Steering gear <u>connections</u>	Cargo Hatches <u>to</u> <u>Itan</u>	Masts, Yards, &c. _____
" " in way of sidelights	Windlass	Hatches	Condition, how ascertained (State if wedges removed.)
Frames	Have pumps been examined and found efficient?	Planking	Equipment letter _____
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Anchors, No. of _____
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	Cables (State if now ranged) _____
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" length _____ mean diamr. _____ (on board.)
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	" Rule length _____ size _____
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Chain Locker _____
Stringers		" " at other places	Hawsers & Warps _____
Inner Bottom Plating		Stringers, Clamps & Shelves	Standing and Running Rigging _____
Have the Tanks been examined Internally?		Salting	Sails _____
Have the Tanks been tested?		State if examined	

General Observations, Opinion as to Class, Recommendation, &c. :
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."
This vessel, so far as now seen, is in an efficient condition, & eligible in my opinion to remain as classed, without fresh record of survey, but with the notation of S.S. & date when the survey is completed.

Survey Fee (per Section 23) _____ £	Fees applied for, _____
Special Damage or Repair Fee (if any) (per Sec. 23) _____ £	10 _____
Travelling Expenses (if chargeable) _____ £	Received by me, _____
Second Surveyor's Fee (if any) _____ £	10 _____

Committee's Minute LIVERPOOL 28 APR 1954
 Character Assigned Deferred for compl. S.S.

Surveyor to Lloyd's Register of Shipping. J. Whittle



It so, is the Report sent now, or when will it be sent?

Transfer Ink. (MADE AND PRINTED IN ENGLAND.)
 20m, 1250. The Surveyors are requested not to write on or below the space for Committee's Minutes.

Is Certificate required? If so, to be sent to