

## LLOYD'S REGISTER OF SHIPPING

6512

Port SourabayaDate 5th February 1963

This is to Certify that I have

surveyed the M.V. GLORY 2271 Gross tons of Singapore

whilst the vessel lay afloat at Sourabaya on the 29th January 1963 and subsequently for the purpose of deck repairs and condition of class,

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am

recommending that she be as classed without fresh record of survey subject to the trunk deck plating on the port side of No 3 Hatch between frames 8-18 (Counting from fore bulkhead of No 3 Hold) being examined and dealt with as necessary at the coming Special Survey and subject to any outstanding conditions of class being dealt with as previously recommended.

S. R. KHARE

S. R. Chare

Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

AS Annual Survey  
 BIS Biennial Survey  
 DS Docking Survey  
 NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
 SS(Dr) Hull Special Survey (Drilling)  
 SS(M) Hull Special Survey (Modified)  
 CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."