

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 15 JUNE 1931 When handed in at Local Office 15 JUNE 1931 Port of LIVERPOOL

No. in Reg. Book 81145 Survey held at Birkenhead. Date, First Survey and Last Survey June 10, 1929

TONNAGE: GROSS 466, UNDER DK. 466, NET 285. Built at Dundee. By whom Waledon S.B. & Co. Ltd. Owners: The Mayor, Aldermen & Burgesses of the Borough of Wallasey. Managers: [Signature]

Surveyed Afloat or in Dry Dock? Yes Name of Dock Birkenhead Dry Dock. Destined Voyage WB=CellDBorDBa feet; uE&B feet; f feet total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements). CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned how long. Machinery and Boiler Surveys (including date of N.B., if any).

Last Report, No. 97094 Port Lw. Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking. Vessel placed in dry dock. Bottom and rudders cleaned, examined and recoated. Decks, vents, casings etc examined and found good.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Paired or Repaired								
Paired or Repaired in place								

PRESENT CONDITION OF THE	
Decks	Good
Caulking of Decks	"
Coamings	recoated
Beams & Fastenings	Good
Breasthooks	"
Transoms	recoated
Frames	"
Reverse Frames	"
Longitudinals	"
Transverses	"
Floors	recoated
Keelsons	"
Stringers	"
Inner Bottom Plating	"
State if Tanks have been examined inside	no
State if Tanks now tested	no
Bulkheads	recoated
Ceiling	"
Cement or Asphalt (State which.)	"
Rudder	Good
Steering gear and its connections	"
Windlass	"
Have Pumps now been examined and found efficient?	no
Have Sluice Valves now been examined and found efficient?	no
Have Watertight Doors now been examined and found efficient?	no
Have Ventilators and their Coamings been examined and found efficient?	yes
Dblg. Plates under Sounding Pipes	"
Engine Room Skylights	Good
Cowls, Bunkers, Open'gs, Lids, &c.	"
Scuppers	"
Cargo Hatchways	"
Hatches	"
Planking of Wood Vessels	"
Caulking ditto	"
Trenails ditto	"
Breasthooks & Stems ditto	"
Transoms, Pointers, & Catches ditto	"
Timbers of Frame at openings ditto	"
Ditto ditto at other places ditto	"
Stringers, Clamps & Shelves ditto	"
Salting ditto	"
Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year	"
Boats	Good
Masts, Yards, &c.	None
Condition, how ascertained	"
(State if wedges removed)	no
Sails	"
Equipment letter	"
Anchors, No. of	2
Cables (State if now ranged)	no
" length (on board) size	Stated to be
" Rule length	Correct
Hawser & Warps	Good
Standing and Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel, so far as now seen, is in good condition and is eligible in my opinion to remain as classed with fresh record of Survey 6.31.

Survey Fee (per Section 29)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me.	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

LIVERPOOL 16 JUNE 1931. Character Assigned 100A1-6.31. Bkn. with fld. for ferry service ERK. Surveyor to Lloyd's Register of Shipping H.B. Murray.



Has a survey also been held on the machinery of the ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so, to be sent to