

LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780

RE-CONSTITUTED 1834

LLOYD'S MACHINERY CERTIFICATE (LMC)

This is to Certify *that the Machinery of the*

Motorship "LA ESTANCIA"

9486 Tons, of London

has been Specially Surveyed by the Surveyors to this Society during construction at Le Havre

and was reported to be on the 29th April, 1960 at La Seyne-sur-Mer
in good working condition.

The Record ✕ **LMC** *has been made in the Register Book, subject to Periodical Surveys as required by the Rules.*

PARTICULARS

| | | |
|---|--|---------------------------------------|
| Description of Machinery | Oil Engine 2 Stroke Cycle Single Acting | |
| Makers of Main Engines | Soc. des Forges et Chantiers de la Mediterranee | |
| Makers of Main Boilers | - | |
| Approved pressure of Main Boilers | - | lb. per square inch saturated steam |
| Steam Temperature | - | lb. per square inch superheated steam |
| Approved pressure of Aux. Boilers Boilers | 85 | lb. per square inch |
| Approved pressure of Steam Heated Steam Generators | - | lb. per square inch |
| Approved total | B.H.P. 5800 | 125 r.p.m. of Engine |
| | S.H.P. - | at 125 r.p.m. of Propeller |
| <p>The main engine is not to be operated continuously between 50 RPM and 55 RPM when the spare cast iron propeller is fitted.</p> | | |

Witness my hand


W. J. Ferguson
Secretary

Herbert A. Kelly
Chairman

71, Fenchurch Street, London, E.C.3. 7th October, 1960.

This Certificate is issued upon the terms of the Rules and Regulations of the Society to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register
Foundation

M/M. 11030



© 2021

Lloyd's Register
Foundation