

Des paid.
Lloyd's Register of Shipping,Willemskade, 11^B,

Rotterdam, 29th September, 1938.

(Postbox 701.)

LLOYD'S REGISTER
Received
30 SEP 1938
Ansd.

Dear Sir,

With reference to your classing letter of the 16th instant, respecting the m.v. "MURON", I have to inform you that the fuses are not on the live side of the switches.

With regards to the generator certificates, The Contractor had supplied a Elin generator and has informed us the generator was tested at the factory in Germany, however, the test certificate has not yet been forwarded, but will be sent to you as soon as received.

I am, Dear Sir,

Yours faithfully,

W. H. Bounce

The Secretary,

LONDON.



© 2021

Lloyd's Register
Foundation

011647-611056-0045

Referred to the Chief Engineer Surveyor
Referred to Mr. HILL

Referred to Mr. HILL

30 SEP 1938

LONDON.
The Secretary,

YOUR TELETYPE,

I am, Dear Sir,

forwarded, but will be sent to you as soon as received.
Germany, however, the test certificate has not yet been
informed as the generator was tested at the factory in
the compressor was supplied a Elin generator and has
with regards to the generator certificate,

sides of the switches.
have to inform you that the fuses are not on the line
of the lock instant, respecting the M.A. "MOTOR", I
of the lock reference to your closing letter

Dear Sir,

(Postbox 101)

Rotherham,


28th September, 1938.

William,

Kind regards,
W. H. H. H.

TELEPHONE NOS. 20212 & 20303

TELEPHONE NOS. 20212 & 20303



© 2021

Lloyd's Register
Foundation