

Received from Chief Ship Surveyor

SHIP'S NAME 'KOSTRENA' REPORT Spt. No. 1631

Standing Conditions of Class: Subject to 15 fathoms of <sup>worn</sup> chain cable  
being replaced at the earliest opportunity.

Reform of Class (B) (As before or None)

Structure of Present Survey: (Afloat and in dry dock) Docking.  
Damage repairs (contact).

Recommendation: SUBMITTED record of docking 8,52 be assigned,  
subject as above, and to the rudder or rudder  
head (one piece) being renewed by 2,53.

8,52 Spt. Subject.

*SAH*  
19-9-52



© 2021

Lloyd's Register  
Foundation

011047 011056-0137