

EL'S NAME

HRVATSKA

SPLIT

Report 8/10/46

No. 1026

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in DECIMALS of an inch.

STRAKE.	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
FORECASTLE J	.20	.30	.30	-	-	.20	.30	.30	-	-	.20	.30	.30	-	-	
E SHEER STRAKE	H	.20	.30	.30	-	-	.20	.30	.30	-	-	.20	.30	.30	-	-
below.....	G	.55	.65	.62	-	-	.40	.47	.48	-	-	.40	.45	.49	-	-
STRAKE	F	.35	.35	.37	-	-	.30	.32	.34	-	-	.30	.30	.35	-	-
like below	E	.40	.40	.30	-	.10	.30	.32	.34	-	-	.30	.35	.35	-	-
"	D	.40	.33	.35	.07	.05	.30	.34	.31	-	-	.30	.35	.35	-	-
"	C	.40					.30					.30	.35	.35	-	-
"	B	.35					.30					.30				
WHEELPLATE A	.45						.40					.40				
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																
"																

\* PLATES HAVE NOW BEEN RENEWED

Drillings at ends to be made in the vicinity of the peak bulkheads.

© 2021

Lloyd's Register  
Foundation  
011047-011056-0145