

113 Diesel

2

2 JUL 1930

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

M. T. P. Lord Willington

Rpt.

Cal

No.

7087

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

S.S. No. 1

The

S.S. No. 1

has now been held, and the following repairs

done due to wear and tear:-

Minor repairs effected.

It is submitted the vessel is worthy to remain as classed, with record of Survey 5. 30 and notation of S.S. 701. 30 as recommended.

A. 1

Bridges

5. 30

Cochin

to Cochin 701. 30

Fitted for air fuel etc

PM
2.7.30



© 2021

Lloyd's Register Foundation

011047-01056-0242