

Received from Chief Ship Surveyor

23 MAY 1955

SHIPS NAME "CHRYSSI" REPORT Sng. No. 10689

Outstanding Conditions of Class: NONE.

Endorsement of Class (B) (~~As before~~ or None)

Nature of Present Survey: (Afloat and in dry dock)

Docking: Damage repairs (stevedore, collision & H.W.).

Recommendation:

SUBMITTED record of docking 3,55 be assigned, subject to port and starboard longitudinal bulkheads of No.10 cargo tank (leakage) being examined and dealt with as necessary next drydocking.

3,55 Sng. Subject.

DELETE FROM S.R.L.  
(Next docking survey becomes due 5,55.)

Rev'd Shingles angle,  
one deck seams, sheerstrake  
seams, two bilge seams,  
one bottom seam.

*[Signature]*  
6-5-55

Part A-B. steel "C" type - In order

Blk (new)

© 2021

Lloyd's Register  
Foundation

011047-011056-0334