

5th December, 1958.


HALIFAX

7442 - As recommended.

7450 "RUPERT BRAND III" As recommended, except that it is considered that in this and future similar cases a DS record should be assigned. You should, therefore, issue an amended Interim Certificate with a record of DS 11,58, especially in view of the condition of class which has now been imposed.

It is concluded that the shell plating, rudder and stern-frame etc. were examined and found in good condition, but your confirmation is desired.

I also have to inform you that in this and future similar cases Tables 1 and 2 of the report should be completed where applicable.



Lloyd's Register
Foundation

011057-011061-0293