

Received from Chief Ship Surveyor.....

2 DEC 1958

SHIP'S NAME "RUPERT BRAND 111"

REPORT

Hfx.

No.

7450

standing Conditions of Class: NONE.

Alterment of Certificate (~~As before or None~~)

Location of Present Survey: (~~Afloat and in dry dock~~)

Docking: Repairs to damage (grounding).

Recommendation:

SUBMITTED record of 'DS 11, 58' be assigned, subject to set up shell plates A.2 & 3 (p.s.) being permanently repaired next drydocking.

DS 11, 58 Subject

IT IS FURTHER SUBMITTED the Halifax Surveyors be advised, in this and future similar cases it is considered a 'DS' record should be assigned, and in view of the condition of class be requested to issue an advised Interim Certificate.

They should also be advised it is concluded the ship was examined at this time and that the shell plating, rudder and sternframe etc. found in good condition, but confirmation is desired. In future similar cases Tables 1 & 2 of the report should be completed where applicable.

see letter dated 9/12/58

DA. 1/12/58.