

BRITISH CORPORATION

17 DEC 1949

Chief Ship Surveyor

Received from Chief Ship Surveyor

S NAME CAPTAIN MIKES REPORT Pir. No5551

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This ship is classed BS (Tanker, Mediterranean Service).

An Annual (Classification) Survey became due 3.49.

The PIRAEUS Surveyor reports (11.49) vessel afloat and the shell plating above waterline found wasted and wavy.

The shell bottom plating in No. 1 cargo tank found badly pitted and several shell frames thin (previously reinforced), also beams wasted and wavy.

The fore well deck plating in way of cargo tanks pitted and doubled places.

It is considered the above defects should be dealt with at the earliest opportunity and the Owners' Representative stated that a further examination would be made and repairs effected on completion of the present charter at the end of December 1949.

It is submitted ACTION be DEFERRED for Annual Survey and outstanding repairs. by 12.49.

da Bay 10/12 for Heraklion



3021
12
49.

011062-011070-0333

Lloyd's Register
Foundation