



La correspondencia  
debe dirigirse a los  
Inspectores.

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E. C. 3.

Calle Gran Vía 83, 1.º izqda.

Apartado de Correos No. 286, Bilbao.

Telegramas: Register, Bilbao

Teléfono ~~1699~~ 16995

13th. February, 1956.

Classn(S) Dear Sir,

S/S. "MARQUES DE URQUIJO"

Bbo. Rpt. No. 11852

RECEIVED

20 FEB 1956

We regret very much our omission of the  
notation s.p.s. 12,55.

The shell plate thickness of 8.mm. in F strake  
(p.s.) forward, is local, general condition of the plate  
is good.

The actual diameters of the main engine  
cylinders are:- H.P. 529.5 mm., M.P. 966.2 mm., L.P.  
1564 mm.

Yours faithfully,

For the Surveyors.

The Secretary,  
LONDON.

with.

The thicknesses of shell plating as ascertained by drilling  
are as shown above and together with the renewals indicated are

011071-011078-0113

Lloyd's Register  
Foundation



SPER

CLASSIFICATION

To R/B

Main engine cylinders

H.P. 529.5  $\frac{1}{2}$  in, 170.966  $\frac{1}{2}$  in

L.P. 1564  $\frac{1}{2}$  in - 1006 mm

H

GO. 13/5/56

800 655 9.55

Rollers

2.3.56

4/5

For Mr. G. G. G. G.

Roll



© 2021

Lloyd's Register  
Foundation

Nature

BILBA  
11864  
12,555  
plate  
of 10  
plate  
to th  
glad  
shou  
that