

23 OCT 1961

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

P/S NAME DOM JOSE PA
"SAO PAULO"

REPORT

RIO.

No. 8075

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

The class of this ship ~~Al~~ "With Freeboard" "For Service between Trinidad and the River Plate" was expunged from the Register Book 1,60., for non-compliance with the Rules.

The RIO DE JANEIRO Surveyors report (6,61) this ship placed in dry dock, the requirements of a Special Survey (C) for Reclassification complied with and repairs effected to a number of shell plates and other items.

IT IS SUBMITTED the ship is eligible to have her class ~~Al~~ "With Freeboard" "For Service between Trinidad and the River Plate" reinserted in the Register Book, and to have record of DS 6,61 and Notation of SS 6,61 assigned as recommended, together with particulars as formerly.

REINSTATE CLASS IN R.B.

~~Al~~ "With Freeboard" "For Service between Trinidad and the River Plate".

DS 6,61
SS 6,61

INSERT IN R.B.

Particulars as formerly.

Moulded Dimensions:-

L. 330'-0" B. 54'-0" D. 27'-0"

E.B. 54'-2"

R.O.F. Nil.

O.F. 8.54

AMEND R.B.

FROM:- (✓) 2"

TO:- ✓

IT IS FURTHER SUBMITTED before this case receives the consideration of the Committee, the Surveyors be advised of the former conditions of class and be informed it is concluded these were dealt with, but confirmation is desired.

CRMP.
12.10.61.



© 2021

Lloyd's Register
Foundation

011071-011078-0164