

Bronze Liners, thickness in way of bushes

as fitted

Thickness between bushes

as per Rule

as fitted

Is the after en

propeller boss

If the liner is in more than one length are the junctions made by fusion through the whole thickness

ne  
or

Nos 7614772 Made by J. G. Kincaid & Co.

11860

Lithgows Steel Yel. 1011 Trans. Ferry. No. 3023

Certs Report No.


certificates

It is submitted that a copy of these ~~Report~~ <sup>certificates</sup> be forwarded to the ~~Returned~~ <sup>Retained</sup> Surveyors for their guidance and for completion. as the completion of the vessel has been suspended.

Date

19/10/45

© 2021



Lloyd's Register Foundation

compartment to another

Yes

Is the Shaft Tunnel watertight

Yes

Is it fitted with a watertight door

No

AIN BOILERS, &c.—(Letter for record) Total Heating Surface of Boilers

5325 sq ft x 2 = 10650

Which Boilers are fitted with Forced Draft

Speed Steamboiler