

screw shaft fitted with a continuous liner the whole length of the stern tube ..... Is the after end of the liner  
propeller boss ..... If the liner is in more than one length are the joints burned ..... If the liner does not fit tight  
in the bearings in the stern tube, is the space changed

5/8 River Clyde (Blt 1905)

These two main boilers were removed from this vessel after she was wrecked & fitted on board the 5/8 Polperro see Malta Rpt No 1020 (in guard book)

Upon being reclassified she was supplied with new boilers — see papers Rpt 1963 dated Febr 1921.

The boiler plans referred to above have been transferred to bag attached to Malta Rpt 1020

1.12.23

011071-011078-0261



© 2021

Lloyd's Register Foundation

the bilge suction pipes, cocks, and valves arranged so as to prevent any communication between the sea and the bilges  
were stern tube, propeller, screw shaft, and all connections examined in dry dock ..... Is the screw shaft tunnel watertight  
fitted with a watertight door ..... worked from .....