

DISCLOSED SECTION No. 576

Rpt. 8.

(Received at London Office)

LON No. 129 of A

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of LONDON

No. in Reg. Book 54583 on the Wood, Iron or Steel MY. BULLINA Date, First Survey... Last Survey... 19... (No. of Visits...)

Built at Sunderland By whom J. L. THOMPSON & SONS LTD When 1945 YEAR. MONTH. 10

Owners SEE CORRESPONDENCE Owners' Address... (if not already recorded in Appendix to Register Book)

Managers... Port belonging to SEE CORRESPONDENCE

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER: \* for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any).

1100 A1 1-53 ss SNG - 1149

PLMC CS 1149 DBS 1-53 TSC 5-51

Carrying Pet. in Bulk Butts of Shell - all plating elec Welded

LAD UP - SURVEYS OVERDUE

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE FOR

Summary of Damage Repairs: Shell Plates, Frames, R. Frames, Floors and Bracket Floors, Beams, Inner Bottom Plates, Dk. Plates, Other Items

Table with columns for various ship components and their repair status.

PRESENT CONDITION OF THE: Bulkheads, Ceiling, Cement or Asphalt, Rudder, Steering gear and its connections, Windlass, Have pumps been examined and found efficient?, Have Sluice Valves been examined and found efficient?, Have Watertight Doors been examined and found efficient?, Have Ventilators and their Coamings been examined and found efficient?, Air and Sounding Pipes, Doubling Plates under Sounding Pipes, Engine Room Skylights, Coal Bunkers, Openings, Covers, &c., Oil Bunkers, Scuppers, Cargo Hatchways, Hatches, Planking, Caulking, Treenails, Breasthooks & Stemson, Transoms, Pointers & Crutches, Timbers of Frame at openings, Stringers, Clamps & Shelves, Salting, State if examined, Copper, or Y.M., When fitted, Month, Year, Boats, Masts, Yards, &c., Condition, how ascertained, Equipment letter, Anchors, No. of, Cables, Rule length, size, Chain Locker, Hawsers & Warps, Standing and Running Rigging, Sails.

### General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23) £ : : Fees applied for, 19

Special Damage or Repair Fee (if any) (per Section 23) £ : : Received by me, 19

Travelling Expenses (if chargeable) £ : : Second Surveyor's Fee (if any) £ : :

Committee's Minute

Character Assigned

Wrote for (copy)

WEDNESDAY 29 APR 1955

Black Line

GENERAL COMMITTEE Thursday, 12th May, 1955. Decision confirmed.

30m, 754 Transfer Ink. (The Surveyors are requested not to write on or below the space)

Is Certificate required? If so, to be sent to

