

1

18 MAY 1933

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel Tw. Sc. "SAUREL"

Report

Lon

No.

98695a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due


The Screwshaft Survey became due in 12,32.

In reply to enquiry the Montreal Surveyor now forwards a copy of a letter from the Owners reading as follows:-

"In reply would advise that these tailshafts were drawn
"in June last - no notification was sent to your Office in this
"respect as, following the usual practice of the Department in
"these matters, it is not proposed to retain this vessel in class".

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...



16.5.33



© 2021

Lloyd's Register
Foundation

011029-011098-0219