

5c.7.31.

F.E.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *Slt. Tw. Sc. "CAMPILO"* Rpt. *Val* No. *300*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st LONG.

~~Transverse~~ No. *7590*Depth "d" *1*Framing: Table No. *1*Description *Longitudinal Framing*2nd Longitudinal No. *25327.5*Proportions Length *14.34*  
Depth =~~Deck~~ Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1 "Carrying Petroleum in Bulk"  
"Longitudinal Framing", "Bracketless System"  
1 Dk

Cell DB & E. 67' 2 1/4 t, FPT 46 t, APT 94 t, DTF 18' 1/4 5 t  
FK, 14 BH, Lloyds A & C.P.

P 94', B 33', F 31'  
mach. aft.



© 2020

Lloyd's Register  
Foundation

011120-011129-0183