

Rpt. 8

## REPORT OF SHIP SURVEYS AND REPAIRS

Received London

Ship's Name SS/MS 'E B R O'

Gross tons 7120.

Is there a rpt. 9? No.

Port Antwerp.

Rpt. No.

No. of visits 2.

First date 13.11.62.

Last date 14.11.62.

Interim Cert. issued  
& copy herewith? Yes.Damage rpt. issued  
& copy herewith? No.

Last rpt. (H.Q. only)

Date of  
completing rpt. 15.11.62.

Surveyed at, if different from Port above --

Surveyed afloat  
and/or in D.D. Afloat.

Last date of examination in D.D. --

Has a Load Line  
Survey been held? No.

Freeboard Marks verified --

State which additional Rpt. 8 is attached: (Cont); (PS); (DE); (EQ); (Rig)

Survey fees

Damage fee 2.500

Expenses

S.A. fee

I have surveyed the above ship in accordance with the Rules for DAMAGE stated to have been caused by contact with pier at Calais on the 11th. November 1962.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.  
Found.

Stem barset over in way of 5th. strake below sheer and a number of rivets in way started.

Now done.

As temporary repair plate edges welded to stem bar and started rivets ring welded port and starboard.

It is submitted that the above damage be further examined and dealt with as found necessary at next drydocking.

Survey confined to above.

I recommend that this ship remain as classed with/without fresh record of dry docking subject to No. 1 plate (port and starboard from forward) in 5th. below sheer and stembar in way being further examined and dealt with as found necessary by the next drydocking, and any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee THURSDAY 20 DEC 1962

Minute

LS 11.62 Subject

MBS. 6.62

J. COATES  
Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

011140-011148-0028