


PARTICULARS OF PROTECTION TO OPENINGS, ETC.

Hand-drawn plan of the ship 'H.M.S. 'Albatross'' showing the layout of the hull. The ship is oriented horizontally with the bow on the left. The hull is divided into several compartments. From left to right, the compartments are: Accommodation (Accom), No. 5 Turn.dk. (deck) and No. 5 Hold., No. 4 Turn.dk. and No. 4 Hold., Engine Room, Boiler Room, No. 3 Turn.dk. and No. 3 Hold., No. 2 Turn.dk. and No. 2 Hold., No. 1 Turn.dk. and No. 1 Hold., and a Store compartment. A dashed line runs along the top of the hull, labeled 'Fbd dk.' (fore-deck) at the bow and '2nd dk.' (second deck) at the stern. A small structure labeled 'Ash 3' and 'Shoat' is located between the Engine Room and Boiler Room. The ship's name 'H.M.S. 'Albatross'' is written at the top left.



Particulars of Flush Bunker Scuttles:—

None.

Particulars of Companionways :— All companionway doors operated from both sides.

One skylight to crew space aft 3'-6"x2'-0", coaming .30"x16" above wood deck with hinged steel covers.

Particulars of Ventilators in exposed positions on freeboard and superstructure decks :—

2-5
All ventilators fitted with food plugs and canvas covers.

Particulars of Air Pipes in exposed positions on freeboard, ~~raised quarter, or superstructure~~ decks:—

All air pipe openings 30" above deck and fitted with wood plugs and canvas covers.

A new form should be prepared if any alterations that affect the freeboard have been made. If no such alterations have been made, the Surveyor should endorse the form on this side with his signature and the date.

Trade of ship General.

Names of sister ships Standard North Sands Type.

Builder's name and yard number Davie Shipbuilding & Repairing Co. Ltd., Larzan, P.Q. Hull No 543

Owners Park Steamship Co. Ltd.

Fee ☒ \$100.⁰⁰



© 2021

Lloyd's Register
Foundation

0069 1/2