

1m, 12, 20.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

S. S. "Lowana"

Report

G.K.

No. *18756*

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

1st Entry

When due

+ 100A1 (Steel) "Shelter deck with freeboard" subject to one indented shell plate being fitted at Owners convenience.

1 Dk (stl.) & Shelter Dk (stl.)

Call D. B. 288' 745² F.P.T. 93² A.P.T. 5¹/₂

F.K. Collision B.H. to Shelter Dk. 4 B.H. to Upper Dth

Len. Lloyd's A.T.C.P. F 31'

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be entered in the Register Book.

[Signature]

[Signature]
11-7-24



© 2021

Lloyd's Register
Foundation

011140-011148-0091