

"ARABIAN QUEEN"

The class is subject to single-pole switches in accommodation and engine room being changed to double-pole switches at the first opportunity and the case reviewed by the end of 6.48.

On enquiry from the Gothenburg Surveyors they state that the Owners have not yet been able to obtain the necessary double-pole switches yet, but it is hoped for this matter to be dealt with within the next six months or so.

It is submitted ACTION be DEFERRED.



Row
© 2021

30.7.48

Lloyd's Register
Foundation