


Surr. should specially examine
connections at ends of the four
deck girders and report to this
Office

(per Mr. Shephard)

[Signature]



14.10.47

© 2021

Lloyd's Register
Foundation