

the vessel was brought head on to wind and tide; movement was observed at the forecastle deck, this was further investigated and it appeared as though the vessel was "working"

ADDRESS, "REGISTER, GLASGOW."

TELEPHONE: CENTRAL 6491 (4 LINES).

Lloyd's Register of Shipping,

95, Bothwell Street,

Glasgow, C.2. 9th October, 1947.

Dear Mr. Shephard,

L.C.T. "ADULIS".

Referring to previous correspondence regarding the above vessel, I visited Grangemouth yesterday to examine the sister vessel now being altered, and I met Mr. Kennedy, representing Sir J. Biles & Co., who told me he had heard that the vessel had passed Algiers ^{and had made} at an average speed of $10\frac{1}{2}$ knots!! This is very re-assuring information, and our original doubts seem to require some further investigation.

On examining the sister vessel No. 796, I found that the tapering off of the strength of the four deck girders was unsatisfactory and I have arranged to have this rectified.

At the after end all four finish on the front of the erection with only a small angle stiffener with a vertical bracket at the top, on the inside.

It has been agreed that the accommodation in way will be re-arranged so that the web frames can be fitted to back up the girders and that if possible these should be carried down to the bottom of the ship. At the forward end the two inboard girders stop short of the forecastle and their strength is tapered off, which seems to be satisfactory, but the two outboard ones simply stop on a thin bulkhead plate with no backing at all inside. It has been agreed to fit web plates here also and to carry these down to the bottom of the ship.

I think this sudden discontinuity of strength might be the explanation of the excessive working of the vessel and I suggest that if you are arranging for the "ADULIS" to be examined on arrival at her destination, these parts should be specially examined.

Yours sincerely,

R.B. Shephard, Esq., B.Sc.,
LONDON.

© 2021
Lloyd's Register
Foundation

01161-01170-0148

Submits the conveyance as part of
destination to address as per last paragraph
of this letter.

Cable

sent.

13-10-47

RSD

(See Letters on
R.R.C. 14.10.47)



TELEGRAMS RE

© 2021

Lloyd's Register
Foundation

COPY