

FEB 1932

s. s. "VIOLET"

London 97155a


The screwshaft survey became due in 10,31.

The Society's Surveyor at Penang has now written that he has been informed by the Superintendent of the Federated Malay States Railways, the Owners, that it is not their intention to continue the vessel's classification.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book, and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...



3.2.32.



© 2021

Lloyd's Register
Foundation