

4E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME "MATWARA"

Rpt.

N.S.W. No. 4854

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey ~~REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH~~

The class is subject to the donkey boiler not being used.

The vessel has recently been laid up at Newcastle, N.S.W.

A General Examination, BS and screw shaft survey have been held.

The spare propeller has been fitted and main discharge valve chest renewed.

IT IS SUBMITTED that this vessel is eligible for the Record "Examined 6.46",
BS 6.46,
S 5.46,

Subject to the donkey boiler not being used.

note in S.R.L.
ing electrical
ent.

23. 9. 46.



© 2021

Lloyd's Register
Foundation

011227-011234-0260