

Ship's name "KAMUNI" Port Trd No. 2532

The class is subject to temporary repairs to bottom shell plating in way of E.R. (s.s) being specially examined and dealt with as necessary by the Special Survey.

ACTION is DEFERRED for Special Survey.

There is an S.R.L. Appendix Note.

A SPECIAL SURVEY (C) became due 9,63 and postponement until 9,64 has been previously approved.

The PORT OF SPAIN, Trinidad, Surveyors report (8,64), ship examined in dry dock and fairly extensive repairs recommended. They state that the Owners considered extensive repairs to be uneconomical considering the ship's future commitments, and decided to do a minimum of repairs and take the ship out of class and trade in British Guiana waters only.

In view of the above the case is submitted for the consideration of the Committee whether the class be withdrawn, but ACTION be DEFERRED pending further information.

INSERT IN S.R.L. APPENDIX.

Shell plate in way of frame 14 (p.s. from aft) indented.
Stem plate in way of 5' draft mark indented.

R.F.C.
5.2.65.

