

22nd November, 1960.

KHORRAMSHAHR

RMC 250 - As recommended.

255 "KANGAVAR" - As recommended. It is concluded that you are in error in reporting the mean diameter of chain cable on-board as being $\frac{3}{4}$ ", as the ship was originally supplied with 1.3/16" diameter chain cable, but your confirmation is desired.

 © 2021
Lloyd's Register
Foundation

011251-011258-0053