


AMENDED

COPY

LLOYD'S REGISTER OF SHIPPING



Port OF PIRAEUS,

12th August, 1961.

This is to Certify that I have

Surveyed the Machinery of the S.S. "EMPIRE FAUN" temporarily sailing as "SIRIUS" 846 tons gross of Google whilst lying at Sude Bay, Crete, on the 30th May, 1960 and subsequently on account of Part Engine & Boiler Surveys, Docking and Screw Shaft Survey.

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following

Survey Records be made in the Supplement to the Register Book E.S. 6,60 & MBS 6,60 when the surveys have been completed and subject to tailshaft being renewed before vessel is placed in service.

and that her Machinery Classification Record be continued in the Book.

To complete the Engine Survey.

Electrical installation to examine.

Engine and auxiliary repairs to examine.

Engine to examine under working condition.

Parts now examined: Fire extinguishing arrangements to be tested.

(C.S. Items only)

To complete Main Boiler Survey.

The safety valves to be adjusted under steam.

O.F. burning system and remote controls to be tested.

E.F. Reid

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

011251-011258-0098

© 2021

Lloyd's Register Foundation