

9th August, 1961.

PIRAEUS.

9108, - As recommended.

RMC 9027, "MARATHON" - As recommended, except that as this is an Intermediate survey records of RMC 6.60

5.61

SRMC 6.60 have been assigned and you should issue an amended Interim Certificate accordingly with a copy to this Office.


If a record of RS is desired then one of the diesel engines driving the refrigerating compressors and a gas condenser cooling water pump will require to be examined at the earliest opportunity, and your further comments are desired by return of post. I acknowledge receipt of your letter of the 28th July, the contents of which have been noted.

9093, "ARMATHIA" - As recommended, except that the class has now been amended to @100A1 "With Freeboard" and you should, therefore, issue an amended Interim Certificate and forward a copy to this Office. It is concluded that the freeboard was checked, but please confirm this.

"EVI LIVANOS" - Further to my classing letter of the 3rd August, I have to point out that indented shell plates Nos. 5 and 6 require to be specially examined and dealt with as necessary at the next drydocking and not at the Special Survey as intimated in the above letter.

9081, "EMPIRE FAUN" (temporarily sailing as "SIRIUS") - As recommended, except that the class has been continued subject to the tailshaft being renewed before the vessel is placed into service, and an amended Interim Certificate should be issued to include this recommendation. In this connection I have to draw your attention to the contents of my letter of the 29th June and a reply to my letter of the 3rd August is still awaited.

Furthermore I have to draw your attention to the undue lapse in time between the last date of survey and the date on which your reports were written and shall be glad if you will take more care to report surveys more promptly in future.



© 2021
Lloyd's Register
Foundation