

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port of Düsseldorf,
Breite Str. 29

8th June, 1953

Works No. 62.55.401

This is to Certify that

Klaus Müller and Walter Schönau

the undersigned Surveyor to this Society did at the request of

Messrs. Ruhrstahl A.G. Brackwede

attend their Works on the 3th March, 1953 and for the purpose of
subsequently

inspecting and testing one Class IIB fusion welded air receivers,

made to the order of Messrs. Klöckner-Humboldt-Deutz A.G. Köln-Deutz
and intended forThe material has been tested as required by the rules, and the
scantlings of the air receiver are in accordance with the approved plan.Each air receiver was, in the presence of the undersigned, tested by
hydraulic pressure to 60 Atm. lb. per square inch and
found satisfactory.

PARTICULARS.

RECEIVER NUMBER.	LENGTH.		INTERNAL DIAMETER. IN.	THICKNESS. IN.	TENSILE STRENGTH. TONS PER SQ. IN.	ELONGATION. % IN.....INS.	BENDS. DEGREES.
	FT.	INS.					
1	1730		460	10	as per Rule requirements		

IDENTIFICATION MARK:—

No.	8266
✓ LLOYD'S TEST.	
T.P.	60 Atm. xx Lb.
W.P.	30 Atm. xx Lb.
KM 21.4.53 KM	

Fee £

:

Retested by hydraulic test of 60 kg/cm² and
inspected and found to be tight and in order.
Marked for identification:— H.D. 21.10.55

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."