

Surveyors.....

Received from Chief Surveyors.....

NAME MANNIN

REPORT Liv. No. 133233

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

vey..... When due.....

By special arrangement this ship undergoes Annual Surveys in lieu of Special Surveys.

An Annual Survey has now been held, but the Liverpool Committee have assigned a record of MBS* 5,51. Such a record implies that all the requirements of the Rules have been complied with. According to the report however, this is not the case, nor can the vessel be regarded as 'being' entitled to a CS record as the whole of the machinery has not been examined during the last four years.

It would therefore seem that the records to be assigned should be "Annual Survey 5,51, Blr.S 5,51 and msp 4,51".

The Liverpool Surveyors should however, be asked for their comments.



© 2021

21.7.51.

Lloyd's Register
Foundation

011273-011279-0082

Independent feed pumps, Independent Bilge pumps
Main steam pipes tested to 100 psi