

Received from Chief Ship Surveyor 6 APR 1955

SHIPS NAME "CARNARO"
JD.

REPORT

Nap. No. 5362

Outstanding Conditions of Class: Subject to wasted bottom shell rivets in No.1 keel plate forward being examined and dealt with as necessary by next drydocking, also to a bower anchor (supplied since 7,53) (Cert. 383) being verified with test certificate at the earliest opportunity.

Endorsement of Class (B) (~~ASXHXHXHXHX~~ None)

Surveys due: SPECIAL SURVEY (D) became due 2,55.

Nature of Present Survey: (~~ASXHXHXHXHX~~ in dry dock)

Docking.
Examination of keel plates, as above.

Special Features: It is stated that the ship will be stopped for S.S. and extensive repairs or possibly alterations by 5,55.

Is Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S. or A.S.)

All items.

S.S. to be completed by:


Recommendation:

SUBMITTED record of docking 3,55 be assigned, subject to wasted rivets and strap between Nos.1 & 2 keelplates and slightly set up Nos.3 & 4 keelplates being specially examined and dealt with at the next Special Survey and to a bower anchor (supplied since 7,53) (Cert.383) being verified with test certificate at the earliest opportunity, but further ACTION be DEFERRED for Special Survey.

3,55 Nap. Subject Amended.

IT IS FURTHER SUBMITTED the proposal to postpone the Special Survey (D) until 5,55 merits the favourable consideration of the Committee.

Handwritten signature
31.3.55



011280-011293-0106