

Tonnage under Tonnage Deck ...

Do. of space or spaces between Tonnage Dk.

CLASS

Length from fore part of stem to after part of stern post on summer L.W.L. See Sec. 3 (1a)

as condition of Class } FEET 503.00

Launched 1945

Kaiser Co. Inc. Portland, Oregon.

NN 'MONTMOREAU'

EX CHISHOLM TRAIL

Sm. 10.47. T.2. Tanker.

LAST REPORT NO. 3275 PORT GIB.

Sent to Chief Surveyors GB

Received from Chief Surveyors

T.2. 128399

VESSEL'S NAME S.S. 'CHISHOLM TRAIL' REPORT Liv. No. 128399

For the CHIEF SHIP SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." (Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Special Survey for Classification When due Repairs & Alterations.

This Tanker was built in 1945 and classed with the American Bureau of Shipping. She has now been purchased by British Owners, and Classification with this Society is desired.

(75 fathoms of chain cable to supply).

NOTED.

100A1 "Carrying Petroleum in Bulk" Fitted for oil fuel F.P. above 150°F 1.49 Bkn. S.S. Bkn. 1.49


Classed 1.49.

1 Dk. 2nd Dk in way of Mchy space. "Elec. welded "Longitudinal Draming". Cell DB 79'. 228t. Dtf 32'. 759t. FPT 314t. APT 56t. FK. 14 BH. P 106' B 36' F 56' Mchy aft O.L. 523.5' E.S.D.

"9t" 2 5/16"

25.3.49.

C.S.S. Records Dept. to note. Fractures in Photo



© 2021

Lloyd's Register Foundation

01294-011303-0210

Side Keelsons, No. each side

thickness of Intercostal Plate

Fourth Deck, amidships, Angle, [ ] or [ ]

Spacing

Poop Deck, Angle, [ ] or [ ]